

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/07/2022

Submitted Date:

07/12/2022

Document Number:

701103309**FIELD INSPECTION FORM**Loc ID 312950 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 7125

Name of Operator: BEEMAN OIL &amp; GAS INC

Address: 3401 QUEBEC ST SUITE 9105

City: DENVER State: CO Zip: 80207

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

6 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Stepp, Sarah		wcciassistant@gmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222990	WELL	PR	05/24/1982	GW	081-06352	FEDERAL 1	SI

**General Comment:**

COGCC Routine Inspection Report Summary

Location is in a High Priority Habitat Area.

During this inspection the following compliance issues were observed:

• Weeds covering location and road.

• 3 flow lines running off the east edge of location. 1-3" open ended riser in front of flowline at entrance of location.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location					
<b>Lease Road:</b>					
Type	Access				
comment:	Road covered with weeds.				
Corrective Action	L			Date:	
Overall Good: <input type="checkbox"/>					
<b>Signs/Marker:</b>					
Type	WELLHEAD				
Comment:					
Corrective Action:				Date:	
Type	TANK LABELS/PLACARDS				
Comment:					
Corrective Action:				Date:	
Type	BATTERY				
Comment:					
Corrective Action:				Date:	
<b>Emergency Contact Number:</b>					
Comment:	911				
Corrective Action:				Date:	
<b>Good Housekeeping:</b>					
Type	WEEDS				
Comment:	Weeds covering location and road.				
Corrective Action:	Comply with Rule 606			Date:	08/13/2022
Type	UNUSED EQUIPMENT				
Comment:	3 flow lines running off the east edge of location. 1-3" open ended riser in front of flowline at entrance of location.				
Corrective Action:	Comply with Rule 606			Date:	08/13/2022
Overall Good: <input type="checkbox"/>					
<b>Spills:</b>					
Type	Area	Volume			
In Containment: No					
Comment: <input style="width: 100%;" type="text"/>					
<input type="checkbox"/> Multiple Spills and Releases?					
<b>Equipment:</b>					
Type: Bradenhead	# 1				corrective date
Comment:					
Corrective Action:				Date:	
<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,

Comment:		
Corrective Action:		Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 222990 Type: WELL API Number: 081-06352 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Well shut in during inspection.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701103325	Inspection 701103309 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5801446">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5801446</a>