

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	Rig location entrance sign is adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>		

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 417736 Type: WELL API Number: 123-31736 Status: SI Insp. Status: SI

Cement

Cement Contractor

Contractor Name: Ranger Energy Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____ Circulate to Surface: _____
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 7312 ft. Cement Volume (sx): 100

Good Return During Job: YES Cement Type: G

Comment: Arrived on location at 1550 hrs Ranger Cement crew was rigged up and pressure testing lines to 5,000 psi. CIBP set at 7,312 ft. Perforations at 7,250 ft., begin mixing and pumping 100 sxs type G 15. 8 lbs. cement for Niobrara squeeze, good returns to the tanks.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday 7-12-2022 at approximately 1600 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Inspection due to a Form 42 MIRU Doc # 403096225 & 42 PA Doc # 403096232. Operator: Oxy/Kerr McGee Location name: Bryant Federal 37-30 API #05-123-31736 County: Weld Weather: Clear. Location: Dry. While there, I observed a Multi Well Pad, with active P&A operations at the time of inspection. During this inspection, I observed no compliance issues: See attached photos. I spoke with Oxy Company man Jeremy Duty about current operations (Niobrara Squeeze), Cement volume to be used (100 sxs), Type (G), weight 15.8 lbs, depth of CIBP (7,312 ft.) and perforation depth (7,312 ft.). No follow up site inspection is needed to ensure that the addressed Compliance issues comply with COGCC rules.</p>	revasr	07/12/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702400703	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5801453