

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/12/2022

Submitted Date:

07/13/2022

Document Number:

707600039**FIELD INSPECTION FORM**Loc ID 428456 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

24 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
428457	WELL	TA	03/09/2020	OW	123-35367	North Platte 14-36	TA
428616	WELL	PR	01/01/2021	OW	123-35441	Latham F-J-1HZ	PR
428618	WELL	PR	12/01/2019	OW	123-35443	North Platte X-D-35HZ	PR

**General Comment:**

This is a WELL / TANK BATTERY inspection.

Well(s): 2: Producing | PR ; 1: Temporarily Abandoned | TA.

Battery: Active.

### Location

<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:	Methanol.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	3: wellsites.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Barbed wire.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Surrounded by metal berms.		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Iron pipe.		
Corrective Action:		Date:	
Type	WELLHEAD		

Comment: 3: wellsites. Iron panel.			
Corrective Action:		Date:	
<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 11		
Comment: At wellsites: 2: Sand traps.  At Battery site: 1: Methanol pumps, tanks w/ drip containment. Placards. 2: Methanol bulk tanks w/ drip containment. Placards. 4: ECD scrubbers. 1: Vertical Heater Treater scrubber. 1: Solar power bank.			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment: Crude oil tank vapor line combustor(s). Controls crude oil tank(s) vapors. Pilot(s): ON. Active.			
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment: Associated Centralized Booster Compressor Station serves multiple field production facilities. Has 3 compressors.			
Corrective Action:		Date:	
Type: Other	# 2		
Comment: 2: wellsites. Gas lift injection inlet line.			
Corrective Action:		Date:	
Type: Bradenhead	# 3		
Comment: 3: wellsites. Appears plumbed to surface.			
Corrective Action:		Date:	
Type: Plunger Lift	# 3		
Comment: 3: wellsites.			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 7		

Comment:	2: Gas Sales Allocation meters: Calibration cards indicates calibration within last year. Last calibration: 03/25/2022. Active w/ production.	
	3: Gas lift allocation meters. Calibration cards indicates calibration within last year. Last calibration: 03/25/2022. Active.	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	<100 BBLS	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:	Date:				

Paint

Condition	
Other (Content)	
Other (Capacity)	60 bbls.
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Shares berms w/ crude oil tanks & produced H2O tanks.			
Corrective Action:	Date:			

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:	Date:				

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Shares berms w/ crude oil tanks & produced H2O vaults.			
Corrective Action:	Date:			

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	10	400 BBLS	STEEL AST		40.352353,-104.389715
Comment:	Equalizer lines connect crude oil tanks.				
Corrective Action:	Date:				

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Shares berms w/ produced H2O tanks, vaults.			
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 428457 Type: WELL API Number: 123-35367 Status: TA Insp. Status: TA

**Idle Well**

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.  
Well has downhole CIBP.

COGCC records last production: 12/2019.  
Form 4 on file. TA status: 02/15/2020.  
Form 21-MIT on file. MIT date: 09/21/2020. Approved.

Corrective Action:  Date:

**BradenHead**

Date of Last Brhd Test: 04/11/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:   
End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date:

Facility ID: 428616 Type: WELL API Number: 123-35441 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing | PR.

Corrective Action:  Date:

**BradenHead**

Date of Last Brhd Test: 04/11/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:   
End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date:

Facility ID: 428618 Type: WELL API Number: 123-35443 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing | PR.

Corrective Action:  Date:

**BradenHead**

Date of Last Brhd Test: 04/11/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type:   
End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On TUE 07/12/2022 at approximately 15:02 hrs. I, Bret Evins, conducted an on-site inspection at:  Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC  Location Name: North Platte /14-36  Location ID: 428456  Well Name(s):  North Platte 14-36, Latham F-J-1HZ,  North Platte X-D-35HZ.  API:  123-35367, 123-35441, 123-35443.  Location County: Weld County, Colorado  Weather: Mostly Sunny, dry.</p> <p>While there, I observed:  Well(s): 2: Producing   PR ; 1: Temporarily Abandoned   TA.  Battery: Active.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	07/13/2022

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707600040	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5802162">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5802162</a>