



Inspection Photos  
Location Name: Alva Short A 1  
Location ID: 312075



IMG 01  
Well sign



IMG 02  
Location overview



**IMG 03**  
Electric fence cable



**IMG 04**  
Lube oil has impacted surface material



**IMG 05**

**Agriculture equipment on location**



**IMG 06**

**Weeds in southeast corner**