

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/13/2022

Submitted Date:

07/14/2022

Document Number:

702500229

FIELD INSPECTION FORM

 Loc ID 312075 Inspector Name: Klink, Alex On-Site Inspection 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10679Name of Operator: LOGOS OPERATING LLCAddress: 2010 AFTON PLACECity: FARMINGTON State: NM Zip: 87401**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:15 Number of Comments2 Number of Corrective Actions

-
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**Contact Information:**

Contact Name	Phone	Email	Comment
Rowley, Darren	505-947-4974	drowley@logosresourcesllc.com	All SW field Inspections
, General		regulatory@logosresourcesllc.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214158	WELL	PR	03/07/1956	GW	067-05475	BONDAD 33-9 17	PR
215541	WELL	PR	07/01/2019	CBM	067-07146	ALVA SHORT A 1	PR
411846	WELL	PR	10/15/2010	CBM	067-09715	ALVA SHORT A 3	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location

Overall Good:

Emergency Contact Number:

Comment: 866-598-6220
911

Corrective Action:

Date:

Good Housekeeping:

Type STORAGE OF SUPL

Comment: Landowner appears to be storing agricultural equipment (irrigation pipe) on northeast side of location (IMG 04 and IMG 05). No reclamation variance/surface owner waiver in well file.

Corrective Action: Remove stored agricultural equipment from location and discourage activities by third parties or obtain approved variance.

Date: 08/13/2022

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type OTHER

Comment: Produced water tank is enclosed by wire fencing.

Corrective Action:

Date:

Equipment:

corrective date

Type: Horizontal Heated Separator # 1

Comment:

Corrective Action:

Date:

Type: Plunger Lift # 1

Comment:

Corrective Action:

Date:

Type: Flow Line # 2

Comment: 2" line from wellhead to separator, 2" line from separator to off location.

Corrective Action:

Date:

Type: Ancillary equipment # 1

Comment: Telemetry

Corrective Action:

Date:

Type: Deadman # & Marked # 6

Comment: One rig anchor near produced water tank not properly marked (IMG 03).

Corrective Action: Install proper guy line markers per Rule 1003.a

Date: 07/29/2022

Type: Bradenhead # 2

Comment: Bradenhead is accessible.

Corrective Action:

Date:

Type: Bird Protectors	# 1		
Comment:	Separator vent stack is screened properly.		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Gas meter calibration is within the last year.		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1		PBV STEEL		37.114020,-107.861830
Comment:	Partially buried produced water tank with steel mesh top.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	125 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Earth berm secondary containment.			
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 214158 Type: WELL API Number: 067-05475 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Facility ID: 215541 Type: WELL API Number: 067-07146 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Facility ID: 411846 Type: WELL API Number: 067-09715 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
		Compaction	Pass			
Gravel	Pass					
		Gravel	Pass			

Comment: No observed impact of storm water. Storm water controls seem sufficient at time of report.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500230	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5803684