


Inspection Photos  
Location Name: Cory Jack 33-7 11-2  
Location ID: 306898



IMG 01

Well sign is deteriorated



IMG 02

Location overview





**IMG 03**

**Weeds are established at pump jack and location**



**IMG 04**

**Produced water at wellhead**



**IMG 05**  
**Produced water at wellhead**