

Inspection Photos

July 8, 2022

Operator: Beeman Oil & Gas Inc- #7125

Location ID: 433308

Location Name: Bulldog /17-11H-893

Inspection Document #: 702800438

Moffat County, CO

NWNW Section 17 T8N R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Bulldog /17-11H-893
Location ID: 433308



Photo 1. Photo taken from the Location entrance shows an overview of the eastern portion of the Location.



Photo 2. Photo taken from the Location entrance shows an overview of the western portion of the Location. Photo shows a portion of the pad not necessary for production operations where interim reclamation is required.

Inspection Photos
Location Name: Bulldog /17-11H-893
Location ID: 433308



Photo 3. Photo shows aerial imagery of the Location from Google Earth. Imagery is dated 10/2019. White line indicates a ground track walked during the 7/8/2022 inspection showing the approximate disturbance/unreclaimed area.



Photo 4. Photo shows the “Location Drawing” from document #401412049 which shows an estimate of production areas and interim reclamation areas included in variance request document #401291906. Variance expired 5/1/2022. Interim reclamation is required.



Inspection Photos
Location Name: Bulldog /17-11H-893
Location ID: 433308



Photo 5. Photo taken from the south of the Location shows gully erosion occurring on sparsely vegetated, unstabilized slopes of the Location.



Photo 6. Photo taken from the northeast of the Location shows widespread rill erosion occurring on the cut slope.



Inspection Photos
Location Name: Bulldog /17-11H-893
Location ID: 433308



Photo 7. Photo taken from the southeast of the Location shows gully erosion occurring on sparsely vegetated, unstabilized slopes.



Photo 8. Photo taken from the east of the Location shows gully erosion occurring on sparsely vegetated, unstabilized slopes.



Inspection Photos
Location Name: Bulldog /17-11H-893
Location ID: 433308



Photo 9. Photo shows a methanol tank at the north of the Location with inadequate wildlife protection BMPs on the secondary containment stock tank.



Photo 10. Photo taken at the north of the Location shows inadequate wildlife protection BMPs on the secondary containment stock tank.



Inspection Photos
Location Name: Bulldog /17-11H-893
Location ID: 433308



Photo 11. Photo shows an open pipe at the wellhead.



Photo 12. Photo taken at the north of the Location shows fluid dripping from separator equipment onto the ground.

