

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/14/2022

Submitted Date:

07/15/2022

Document Number:

690103117

**FIELD INSPECTION FORM**

Loc ID 330209 Inspector Name: Maclaren, Joe On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-

**Findings:**

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		COGCCInspections@Oxy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
250826	WELL	PR	04/01/2022	GW	123-18629	NORGREN 14-9J7	PA
446129	LOCATION	AC			-	NORGREN 14-9J7, 14-16J7 O SA 36149565	EG

**General Comment:**

COGCC Engineering Integrity Inspection; Flowline Inspection  
Photo uploaded

**Inspected Facilities**

Facility ID: 250826 Type: WELL API Number: 123-18629 Status: PR Insp. Status: PA

**Flowline**

#1	Type: Well Site	of Lines	
----	-----------------	----------	--

Flowline Description

Flowline Type: Well Site Size: 2" Material: Carbon Steel  
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:  
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

1101. Installation and Reclamation  1102. Operations, Maintenance, and Repair  1103. Abandonment

Comment: Well (Norgren 14-9J7) has been plugged and abandoned; cut and cap operations have been completed. COGCC form 42 notice of start of plugging operations doc #403063929 received 06/01/2022. The wellhead flowline has been removed. The on location dump and process flowlines at facility/ battery have been removed. No flowline risers were observed at the (PA) wellhead or facility/ battery areas. The facility/ tank battery has been decommissioned; tanks and equipment have been removed. (1) OOS gas meter run observed on the east side of location. No Oxy or contract personnel were on location at the time of inspection.

Corrective Action: Date:

Facility ID: 446129 Type: LOCATION API Number: - Status: AC Insp. Status: EG

**COGCC Comments**

Comment	User	Date
As outlined on COGCC form 19 spill report Doc #403099747 received on 07/11/2022: On July 8, 2022, historical soil impacts were discovered below the former separator location during decommissioning activities at the Norgren 14-9J7, 14-16J7 O SA Production Facility. Excavation and assessment activities are ongoing. The affected infrastructure has been removed and will not be replaced.	maclarej	07/15/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690103118	View of facility decommissioned; OOS GMR	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5804772">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5804772</a>