

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/13/2022

Submitted Date:

07/15/2022

Document Number:

700704398**FIELD INSPECTION FORM**Loc ID 474134 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 7125

Name of Operator: BEEMAN OIL & GAS INC

Address: 3401 QUEBEC ST SUITE 9105

City: DENVER State: CO Zip: 80207

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Stepp, Sarah		wccassistant@gmail.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
475041	OFF-LOCATION FLOWLINE	AC	03/02/2022		-	2	AC
477783	OFF-LOCATION FLOWLINE	AC	09/01/2020		-	Wellhead Line 2	AC

General Comment:**COGCC Inspection Report Summary**

On Wednesday 7/13/2022 at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at Beeman Operating Grassy Creek #1 tank battery, at Location # 475041/477783 in Route county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management, Density habitat.

During this inspection the following possible compliance issues were observed:

1. Access road shows signs of lack of stabilization/compaction/erosion.
2. One tank is not labeled.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:	See stormwater		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	One tank is lacking labeling		
Corrective Action:	Provide proper labeling	Date:	08/05/2022
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:	911	
Corrective Action:		Date: _____

Good Housekeeping:		
Type	DEBRIS	
Comment:	Unused ladder on edge of location	
Corrective Action:	Remove debris	Date: 08/05/2022

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	500 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				

Comment:							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	1		STEEL AST		,		
Comment:		Tank lacking labeling					
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth							
Comment:							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	2	400 BBLS	STEEL AST		,		
Comment:							
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth							
Comment:							
Corrective Action:						Date:	
<u>Venting:</u>							
Yes/No	NO						
Comment:							
Corrective Action:						Date:	
<u>Flaring:</u>							
Type							
Comment:							
Corrective Action:						Date:	

Inspected Facilities				
Facility ID: 475041	Type: OFF-	API Number: -	Status: AC	Insp. Status: AC
Facility ID: 477783	Type: OFF-	API Number: -	Status: AC	Insp. Status: AC

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Fail			

Comment: [1.One side of access road shows signs of lack of stabilization/compaction/erosion.](#)

Corrective Action: [Install or repair required BMPs](#)

Date: 08/26/2022

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700704408	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5805034