

Inspection Photos

API: 071-09921

Operator: VECTA OIL & GAS LTD

Inspection Date: 7/15/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09921 | Date: 7/15/2022

Inspection Photos



Photo 1. Facing east toward the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09921 | Date: 7/15/2022

Inspection Photos



Photo 2. Facing north toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09921 | Date: 7/15/2022

Inspection Photos



Photo 3. There is pipe stored on location in preparation of drilling.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09921 | Date: 7/15/2022

Inspection Photos



Photo 4. Facing northeast. A conductor has been set in preparation of drilling. The open culvert needs to be covered up to prevent wildlife or livestock entry.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09921 | Date: 7/15/2022

Inspection Photos



Photo 5. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09921 | Date: 7/15/2022