

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/11/2022

Submitted Date:

07/12/2022

Document Number:

702500212

FIELD INSPECTION FORM

Loc ID 378715 Inspector Name: Klink, Alex On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 69805
Name of Operator: PETROX RESOURCES INC
Address: 12600 W COLFAX AVENUE #C-440
City: LAKEWOOD State: CO Zip: 80215

Findings:

- 19 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Duran, Alicia		alicia.duran@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	
Nystrom, Dusty	(505) 330-1328/ (719) 529-0682	nystrow@yahoo.com	All SW field inspections
Clark, Ryan	303-80303998	ryan@petrox-resources.com	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
301883	WELL	PR	06/01/2020	CBM	007-06274	ELLISON 33-5 29-1	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location

Overall Good:

Emergency Contact Number:

Comment: 303-803-3998
970-878-5594

Corrective Action:

Date:

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds beginning to encroach on interim revegetation area (IMG 06).		
Corrective Action:			Date:
Type	OTHER		
Comment:	Lube oil is impacting surface material (IMG 05).		
Corrective Action:	Remove oily residue and impacted material and dispose of in approved manner per rule 906 and 1002.f.		Date: 07/27/2022
Type	STORAGE OF SUPL		
Comment:	Drill pipe and sucker rods stored on location (IMG 03).		
Corrective Action:	Remove stored equipment per rule 606.		Date: 07/27/2022

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:	Pump jack enclosed by mesh fence.		
Corrective Action:			Date:

Equipment:

Type	Equipment	Quantity	Comment	Corrective Action	Date	corrective date
Type: Pump Jack		# 1				
Comment:						
Corrective Action:					Date:	
Type: Ancillary equipment		# 2				
Comment:	Telemetry, produced water booster pump.					
Corrective Action:					Date:	
Type: Gas Meter Run		# 1				
Comment:	Gas meter calibration is within the last year.					
Corrective Action:					Date:	
Type: Flow Line		# 5				
Comment:	2 2" lines from wellhead to separator, 1" line from separator to prime mover generator, 2" line from separator to produced water, 3" from gas meter run to off location.					
Corrective Action:					Date:	

Type: Prime Mover	# 1		
Comment:	Gas powered		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:	Separator vent stack is screened properly.		
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Bradenhead is accessible.		
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:	One rig anchor not marked (IMG 04).		
Corrective Action:	Install proper guy line markers per Rule 1003.a		Date: 07/27/2022

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	STEEL AST		37.072594,-107.414590
Comment:	Above ground produced water tank.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Earth berm with liner.			
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 301883 Type: WELL API Number: 007-06274 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/12/2021 Annual Brhd Completed?

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: Last reported bradenhead test: 3/3/2021

08/12/2022

Corrective Action: Confirm bradenhead test has been submitted or perform annual bradenhead test per rule 419.c

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Gravel	Pass					
Ditches	Pass					
Compaction	Pass					
		Compaction	Pass			
		Gravel	Pass			

Comment: No observed impact of storm water. Storm water controls seem sufficient at time of report.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403103371	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5801428
702500213	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5801422