

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/19/2022

Submitted Date:

07/19/2022

Document Number:

702400730**FIELD INSPECTION FORM**Loc ID 417708 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
,		COGCCInspections@Oxy.co m	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
417736	WELL	SI	12/01/2020	OW	123-31736	BRYANT FEDERAL 37-30	SI

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	OTHER		
Comment:	Rig location entrance sign is adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 417736 Type: WELL API Number: 123-31736 Status: SI Insp. Status: SI

CementCement ContractorContractor Name: Schlumberger

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging OperationsDepth Plugs(feet range): 985 ft. to 583 ft.Cement Volume (sx): 55Good Return During Job: YESCement Type: G

Comment: Arrived on location at 1300 hrs Schlumberger Cement crew arrived at the same time. Spotted in Cement crew and rigged up. Safety Meeting, fill lines and pressure test lines to 2,500 psi., begin mixing and pumping 55 sxs type G 15. 8 lbs. cement for a shoe plug from 985 ft. to 583 ft., good returns to the tanks.

Corrective Action: _____

Date: _____

BradenHeadDate of Last Brhd Test: 07/06/2022Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 37Fluid Type: GASEnd Surf Csg Pressure: 1

Comment: _____

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 7-19-2022 at approximately 1300 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Inspection due to a Form 42 MIRU Doc # 403096225 & 42 PA Doc # 403096232.</p> <p>Operator: Oxy/Kerr McGee</p> <p>Location name: Bryant Federal 37-30</p> <p>API #05-123-31736</p> <p>County: Weld</p> <p>Weather: Clear.</p> <p>Location: Dry.</p> <p>While there, I observed a Multi Well Pad, with active P&A operations at the time of inspection (pumping a shoe plug from 985 ft. to 583 ft.).</p> <p>During this inspection, I observed no compliance issues:</p> <p>See attached photos.</p> <p>I spoke with Oxy Company man Jeremy Duty about current operations (Pumping a Shoe plug),</p> <p>Cement volume to be used (55 sxs), Type (G), weight 15.8 lbs, depth of Shoe Plug (985 ft. to 583 ft.) during my previous inspection Jeremy duty informed me that they were planning on moving in on 7-7-2022 but had to push it back and wait for authorization to enter the location and start work due to Bald Eagles in the area, and got approved to move in on 7-8-2022.</p> <p>No follow up site inspection is needed to ensure that the addressed Compliance issues comply with COGCC rules</p>	revasr	07/19/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702400731	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5807676