

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/14/2022

Submitted Date:

07/14/2022

Document Number:

697006234

## FIELD INSPECTION FORM

Loc ID 428105 Inspector Name: Peterson, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

9 Number of Comments

1 Number of Corrective Actions

- 
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE****Operator Information:**

OGCC Operator Number: 10658

Name of Operator: CAPTIVA ENERGY PARTNERS LLC

Address: 11838 WEST YALE PLACE

City: LAKEWOOD State: CO Zip: 80228

**Contact Information:**

| Contact Name | Phone | Email                  | Comment |
|--------------|-------|------------------------|---------|
|              |       | ponsager@captivaep.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 428101      | WELL | PR     | 06/01/2020  | GW         | 123-35226 | MCCOY 14-33   | PR          |
| 428102      | WELL | SI     | 03/01/2022  | GW         | 123-35227 | MCCOY 13-33   | SI          |
| 428106      | WELL | PR     | 08/03/2012  | GW         | 123-35229 | MCCOY 2-6-33  | SI          |
| 428107      | WELL | PR     | 07/22/2012  | GW         | 123-35230 | MCCOY 24-33   | SI          |
| 428108      | WELL | PR     | 07/26/2012  | GW         | 123-35231 | MCCOY 23-33   | PR          |

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | WELLHEAD             |       |  |
| Comment:           | x 5                  |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | BATTERY              |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | TANK LABELS/PLACARDS |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

|                    |                         |       |  |
|--------------------|-------------------------|-------|--|
| Type               | TANK BATTERY            |       |  |
| Comment:           | Architectural steel     |       |  |
| Corrective Action: |                         | Date: |  |
| Type               | SEPARATOR               |       |  |
| Comment:           | Architectural steel     |       |  |
| Corrective Action: |                         | Date: |  |
| Type               | WELLHEAD                |       |  |
| Comment:           | Architectural steel x 5 |       |  |
| Corrective Action: |                         | Date: |  |

**Equipment:**

|                                   |   |       |                 |
|-----------------------------------|---|-------|-----------------|
| Type: Bradenhead                  | # 5                                     |       | corrective date |
| Comment:                          | Bradenhead valve is exposed at surface. |       |                 |
| Corrective Action:                |   | Date: |                 |
| Type: Horizontal Heated Separator | # 5                                     |       |                 |
| Comment:                          |   |       |                 |
| Corrective Action:                |   | Date: |                 |
| Type: Ancillary equipment         | #                                       |       |                 |

|                               |  |  |  |       |            |
|-------------------------------|--|--|--|-------|------------|
| Comment:                      | Automation array, solar arrays, ECD scrubber                                     |  |  | Date: |            |
| Corrective Action:            |  |  |  | Date: |            |
| Type: Flow Line               | # 5  |  |  |       |            |
| Comment:                      |  |  |  | Date: |            |
| Corrective Action:            |  |  |  | Date: |            |
| Type: Vertical Separator      | # 2  |  |  |       |            |
| Comment:                      |  |  |  | Date: |            |
| Corrective Action:            |  |  |  | Date: |            |
| Type: Gas Meter Run           | # 2  |  |  |       |            |
| Comment:                      | Calibration card is outdated. Meter not calibrated annually, see attached photo. |  |  | Date: |            |
| Corrective Action:            | Calibrate gas metering equipment annually to comply with rule 430.d.(1).         |  |  | Date: | 10/14/2022 |
| Type: Bird Protectors         | # 7  |  |  |       |            |
| Comment:                      |  |  |  | Date: |            |
| Corrective Action:            |  |  |  | Date: |            |
| Type: Plunger Lift            | # 5  |  |  |       |            |
| Comment:                      |  |  |  | Date: |            |
| Corrective Action:            |  |  |  | Date: |            |
| Type: Pig Station             | # 1  |  |  |       |            |
| Comment:                      |  |  |  | Date: |            |
| Corrective Action:            |  |  |  | Date: |            |
| Type: Emission Control Device | # 2  |  |  |       |            |
| Comment:                      | Pilots are on  |  |  | Date: |            |
| Corrective Action:            |  |  |  | Date: |            |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| PRODUCED WATER     | 1 | 100 BBLs | STEEL AST |         |        |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|----------|---|----------|------|---------|--------|
|          |   |          |      |         |        |

|                    |          |                     |                     |             |       |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| CRUDE OIL          | 5        | 300 BBLs            | STEEL AST           |             |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |
| <b>Paint</b>       |          |                     |                     |             |       |
| Condition          | Adequate |                     |                     |             |       |
| Other (Content)    |          |                     |                     |             |       |
| Other (Capacity)   |          |                     |                     |             |       |
| Other (Type)       |          |                     |                     |             |       |
| <b>Berms</b>       |          |                     |                     |             |       |
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |       |
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |
| <b>Venting:</b>    |          |                     |                     |             |       |
| Yes/No             | NO       |                     |                     |             |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |
| <b>Flaring:</b>    |          |                     |                     |             |       |
| Type               |          |                     |                     |             |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |

**Inspected Facilities**

Facility ID: 428101 Type: WELL API Number: 123-35226 Status: PR Insp. Status: PR

**Producing Well**

|                    |  |  |
|--------------------|--|--|
| Comment:           | <input style="width: 95%;" type="text"/> |  |
| Corrective Action: | <input style="width: 95%;" type="text"/> | Date: <input style="width: 50%;" type="text"/> |

**BradenHead**

Date of Last Brhd Test: 12/09/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 10 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date:

Facility ID: 428102 Type: WELL API Number: 123-35227 Status: SI Insp. Status: SI

**Producing Well**

|                    |  |  |
|--------------------|--|--|
| Comment:           | <input style="width: 95%;" type="text"/> |  |
| Corrective Action: | <input style="width: 95%;" type="text"/> | Date: <input style="width: 50%;" type="text"/> |

**BradenHead**

Date of Last Brhd Test: 12/09/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date:

Facility ID: 428106 Type: WELL API Number: 123-35229 Status: PR Insp. Status: SI

**Producing Well**

|                    |  |  |
|--------------------|--|--|
| Comment:           | <input style="width: 95%;" type="text"/> |  |
| Corrective Action: | <input style="width: 95%;" type="text"/> | Date: <input style="width: 50%;" type="text"/> |

**BradenHead**

Date of Last Brhd Test: 12/09/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date:

Facility ID: 428107 Type: WELL API Number: 123-35230 Status: PR Insp. Status: SI

**Producing Well**

|                    |  |  |
|--------------------|--|--|
| Comment:           | <input style="width: 95%;" type="text"/> |  |
| Corrective Action: | <input style="width: 95%;" type="text"/> | Date: <input style="width: 50%;" type="text"/> |

**BradenHead**

Date of Last Brhd Test: 12/09/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

Facility ID: 428108 Type: WELL API Number: 123-35231 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 12/09/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

| Comment  | User      | Date       |
|--|-----------|------------|
| <p><b>COGCC Inspection Report Summary</b><br/>                     On Thursday 7/14/2022 at approximately 12:15 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the Captiva Energy McCoy Pad 13-33 location #428105 in Weld County, Colorado.<br/>                     While there, I observed that the DCP gas sales meter calibration was outdated. During this inspection the following possible compliance issues were observed: Rule 430.d.(1), with a corrective action date of 10/14/2022.<br/>                     A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.<br/>                     This is a summary of the inspection report.</p> | petersont | 07/14/2022 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 403106390    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5803984">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5803984</a> |
| 697006235    | Photos               | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5803968">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5803968</a> |