

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/13/2022

Submitted Date:

07/14/2022

Document Number:

702500227

FIELD INSPECTION FORM

 Loc ID 312075 Inspector Name: Klink, Alex On-Site Inspection 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:16 Number of Comments3 Number of Corrective Actions

-
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**Contact Information:**

Contact Name	Phone	Email	Comment
, General		sjninspections@ikavenergy.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214158	WELL	PR	03/07/1956	GW	067-05475	BONDAD 33-9 17	PR
215541	WELL	PR	07/01/2019	CBM	067-07146	ALVA SHORT A 1	PR
411846	WELL	PR	10/15/2010	CBM	067-09715	ALVA SHORT A 3	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds on southeast corner of location (IMG 05).		
Corrective Action:	Remove weeds per rule 606.	Date:	07/22/2022
Type	UNUSED EQUIPMENT		
Comment:	Electric fence cable near location entrance is unused (IMG 03).		
Corrective Action:	Use or remove unused equipment per rule 606.	Date:	07/22/2022
Type	STORAGE OF SUPL		
Comment:	Landowner appears to be storing agricultural equipment on southeast side of location (IMG 05 and IMG 07). No reclamation variance/surface owner waiver in well file.		
Corrective Action:	Remove stored agricultural equipment from location and discourage activities by third parties or obtain approved variance.	Date:	09/13/2022

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	OTHER		
Comment:	All equipment enclosed by stock panel.		
Corrective Action:		Date:	

Equipment:

Type			corrective date
Type: Gas Meter Run	# 2		
Comment:	Gas meter calibrations are within the last year.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Linear rod pump		
Corrective Action:		Date:	
Type: Prime Mover	# 2		
Comment:	Electric		
Corrective Action:		Date:	
Type: Ancillary equipment	# 7		
Comment:	Telemetry, electric cabinet, electric control house, 4" risers on west side of location, valve cluster pit, 2 pump control panels.		
Corrective Action:		Date:	

Type: Flow Line	# 7	
Comment:	2 3" and 2 2" lines from wellhead to separator, 2 lines from separator to produced water tank, 4" line from gas meter run to off location.	
Corrective Action:		Date:
Type: Bradenhead	# 2	
Comment:	Bradenhead is accessible.	
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:	Produced water tank vent stack is screened properly.	
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:
Type: Deadman # & Marked	# 6	
Comment:		
Corrective Action:		Date:
Type: Vertical Heated Separator	# 2	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV STEEL		37.113284,-107.861821
Comment:	Partially buried produced water tank.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	95 bbl
Other (Type)	double wall

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Double walled produced water tank.			
Corrective Action:				Date:

Venting:

Yes/No	
Comment:	
Corrective Action:	Date:

Flaring:

Type	
------	--

Comment:		
Corrective Action:	Date:	

Inspected Facilities

Facility ID: 214158 Type: WELL API Number: 067-05475 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Facility ID: 215541 Type: WELL API Number: 067-07146 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Facility ID: 411846 Type: WELL API Number: 067-09715 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
		Compaction	Pass			
Gravel	Pass					
		Gravel	Pass			

Comment: No observed impact of storm water. Storm water controls seem sufficient at time of report.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403106167	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5803686
702500228	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5803683