

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/14/2022

Submitted Date:

07/14/2022

Document Number:

702500231**FIELD INSPECTION FORM**Loc ID 306898 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Overright, Issac		ioverright@maralexinc.com	<a href="#">All SW field inspections</a>
Harrison, Trish	970 759 9545	trishharrison@eis-llc.com	<a href="#">All SW field inspections</a>
Fischer, Alex		alex.fischer@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275103	WELL	PR	08/12/2014	CBM	067-08998	CORY JACK 33-7-11 2	PR

**General Comment:**

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Upon arrival produced water was releasing from wellhead ~1 drip every 15 seconds, a pool 5' by ~3' by 4" deep of standing water was present. The contact number on well sign was contacted and Keegan O'Hare arrived on site to replace pump packing. During the inspection, the produced water was pumped and removed.

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Well sign is deteriorated (IMG 01).		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Weeds established at pump jack and around location (IMG 03).		
Corrective Action:	Control weeds per rule 606.	Date:	07/22/2022
Type	OTHER		
Comment:	Wellhead releasing produced water (IMG 04 and IMG 05).		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.  Remove produced water and dispose of in approved method per rule 906 and 1002.f	Date:	07/14/2022

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Flow Line	# 5		
Comment:	2" line from wellhead to produced water, 1" line from separator to pump jack, 2" line to produced water, 2" line from separator go gas meter run, 2" line to off location.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			

Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	Separator vent stack is screened properly.		
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Pass			
Compaction	Pass					
Gravel	Pass					
		Gravel	Pass			

Comment: [No observed impact of storm water. Storm water controls seem sufficient at time of report.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403106279	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5803794">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5803794</a>
702500232	Photo doc	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5803790">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5803790</a>