

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

07/21/2022

Submitted Date:

07/21/2022

Document Number:

694500443

FIELD INSPECTION FORM
 Loc ID 416625 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10706

Name of Operator: D90 ENERGY LLC

Address: 952 ECHO LANE SUITE 480

City: HOUSTON State: TX Zip: 77024

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Joda, Ken	303-916-3854	ken@d90energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298842	WELL	PR	10/01/2020	OW	057-06480	Surprise 4-06H	EI
298844	WELL	PR	10/01/2020	OW	057-06482	DAMFINO 2-06H	EI

General Comment:

on 7/20/2022 COGCC staff, Kris Neidel inspected the Damfino 2-06 location. This is an Environmental Inspection and does not address down hole. At the time of inspection, excavation crew was on location, enlarging/preparing for a drill rig to move on. The tank battery is unchanged in footprint and number of tanks, some tanks are labeled as out of service, they appear to still be piped to flowlines, the dirt berm has low spots near the load out, the operator should ensure that secondary containment is adequate per rule 603.o (see photos 4 and 5). There is a flare, not lit. an emissions control device and a combustor. Corrective Actions, ensure secondary containment is adequate per rule 603.o. See attached Photos. (photos document the status of flare and combustors)

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	WEEDS		
Comment:	weeds at production equipment and stormwater pond, see photos.		
Corrective Action:	Conduct weed management to prevent further establishment and spread of Noxious Weeds; ongoing weed management required until location passes final reclamation.		Date: 07/28/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 298842 Type: WELL API Number: 057-06480 Status: PR Insp. Status: EIFacility ID: 298844 Type: WELL API Number: 057-06482 Status: PR Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694500444	photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5809449