

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 460669 Type: LOCATION API Number: - Status: AC Insp. Status: AC**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary On Friday 7-22-2022 at approximately 1425 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: This inspection and prior inspection Doc # 702400774 due to a complaint Doc # 403113467. Operator: Civitas/Extraction Location name: Blue Paintbrush Facility Facility # 460669 County: Weld Weather: Cloudy. Location: Dry. While there, I observed a tank battery facility, under construction at the time of inspection. During this reinspection, the following possible compliance issue has been addressed: 602.m Housekeeping: Port A John has been placed on location. See attached photos. No follow up site inspection is needed to ensure that the addressed Compliance issues comply with COGCC rules</p>	revasr	07/22/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702400796	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5810646