

Inspected Facilities

Facility ID: 460669 Type: LOCATION API Number: - Status: AC Insp. Status: AC

Complaint

Comment: Inspection in response to complaint.
 Field Inspector Assigned: Robbie Revas
 Complaint Received
 Date: 07-21-2022
 Complaint Contacted:
 Date: 07-22-2022 Time: 1540 hrs. via email
 Location ID #460669
 Inspection Documents # 702400774 and 702400795
 Complaint Document # 403113467
 Nature of Complaint: No port A John on location.
 Field Inspector Actions:
 On 07-21-2022, I Robbie Revas area field inspector was assigned a complaint received by COGCC staff in reference to no Port A John at a construction site. The complainant Rod Brueske stated the issues were occurring at a Oil & Gas Construction site down the road from his home.
 On 07-22-2022, I sent an email to make contact with the complainant who indicated that on the morning 7-21-2022 he witnessed a worker relieving himself next to his equipment. I performed a site inspection of the oil and gas location and at time of inspection, I did notice that there was no Port A John on location. I spoke with Jeremy, Bull Dozer Operator out on location about it and he made a call and i was told that they would have one out by 7-22-2022. I went out today and there is a Port A John on location.
 Weather conditions: Clear, Location: dry
 No violation of COGCC rules were observed at the time of the reinspection.
 All information reviewed and site inspection information were submitted to the COGCC for further review.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
Inspection due to a complaint, Doc # 403113467	revasr	07/22/2022