

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/22/2022

Submitted Date:

07/22/2022

Document Number:

696304325**FIELD INSPECTION FORM**Loc ID 440312 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10608Name of Operator: TALLGRASS WATER WESTERN LLCAddress: 370 VAN GORDON STREETCity: LAKEWOOD State: CO Zip: 80228**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Stahl, Mike		Mike.stahl@tallgrassenergyllp.com	
Gopsill, Eric		eric.gopsill@bnn-energy.com	
Wolfe, Stephen		stephen.wolfe@state.co.us	
Richard Pitts		richard.pitts@tallgrassenergyllp.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
440313	WELL	TA	09/29/2016	DSPW	123-40777	Razor 21 SWD 1	TA

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adeqaute		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

<b>Good Housekeeping:</b>		
Type	WEEDS	
Comment:	Weeds around Wellhead; see photos	
Corrective Action:	Comply with Rule 606	Date: 08/05/2022

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Other	#		
Comment:	TA Wellhead		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	

<b>Venting:</b>		
Yes/No		
Comment:		
Corrective Action:		Date:

<b>Flaring:</b>		
Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 440313 Type: WELL API Number: 123-40777 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: TA - Last MIT 05.06.2015 - Form 21 402482399 for 5-Year MIT preformed on 09.03.2020 is STILL IN-PROCESS (NOT YET APPROVED).  
Contact COGCC Engineering - Not witnessed, no pressure chart attached. Contacted operator for chart 03.02.2022.  
Emailed again for pressure chart - 7/18/22 No reply yet

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Routine Field Inspection. Weeds around Wellhead. 5-Year MIT NOT YET APPROVED - TA Last MIT 05.06.2015 - Form 21 402482399 for 5-Year MIT performed on 09.03.2020 is STILL IN-PROCESS (NOT YET APPROVED). Contact COGCC Engineering - Not witnessed, no pressure chart attached. Contacted operator for chart 03.02.2022. Emailed again for pressure chart - 7/18/22 No reply yet	petrie	07/22/2022

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696304326	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5810688">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5810688</a>