

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/20/2022

Submitted Date:

07/20/2022

Document Number:

699804711**FIELD INSPECTION FORM**Loc ID 334628 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**16 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273332	WELL	PR	01/09/2005	GW	045-10242	PA 521-6	PR
273334	WELL	PR	12/26/2004	GW	045-10240	PA 321-6	PR
273335	WELL	PR	12/31/2004	GW	045-10239	PA 21-6	PR
286824	WELL	PR	09/19/2006	GW	045-12781	PA 11-6	PR
286825	WELL	PR	09/19/2006	GW	045-12780	PA 311-6	PR
287342	WELL	PR	10/11/2006	GW	045-12978	PA 411-6	PR

**General Comment:**

COGCC Inspection Report Summary  
 On Monday 7/18/22 at approximately 15:00 hours, I, Inspector Corey De Paolo,  
 Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC PA67S95W /6NENW.  
 Location #334628 in Garfield County Colorado.  
 While there, I observed normal production operations.  
 This is a summary of inspection report.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include an attached storage tank. The storage tank is approximately 2'x3'x14' with an approximate capacity of 15 bbl. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 6		
Comment:			
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 6	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 6	
Comment:	No form of pressure monitoring equipment located on braden heads. All braden head valves are accessible.	
Corrective Action:		Date:
Type: Plunger Lift	# 6	
Comment:	All wells on plunger lift	
Corrective Action:		Date:
Type: Bird Protectors	# 3	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities						
Facility ID:	273332	Type:	WELL	API Number: 045-10242	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	273334	Type:	WELL	API Number: 045-10240	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	273335	Type:	WELL	API Number: 045-10239	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	286824	Type:	WELL	API Number: 045-12781	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	286825	Type:	WELL	API Number: 045-12780	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	287342	Type:	WELL	API Number: 045-12978	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing					
Corrective Action:						Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Sediment Traps				
Compaction						
		Compaction				
Gravel						
		Gravel				
Berms						
Ditches						
		Ditches				
		Check Dams				
		Berms				
Sediment Traps						

Comment: Location appears to have some gravel throughout the location with light compaction. Places with light to no gravel are present on location. Light gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<a href="#">Refer to Storm water for comments.</a>	depaoloc	07/20/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699804712	Photos for Insp. #699804711	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5810937">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5810937</a>