

## Dickens 44-14, 2

Document # 702500200

Date completed 7/21/2022

contaminated soil around wellhead cleaned up, tubing picked up

Erosion channels on edge of location repaired and rock runouts installed



Erosion channels repaired and rock runouts installed

