

Inspection Photos

API: 125-06706

Operator: PRIME OPERATING COMPANY

Inspection Date: 7/20/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-06706 | Date: 7/20/2022

Inspection Photos



Photo 1. Facing east at the beginning of the access road. The cattle guard remains and the access road has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-06706 | Date: 7/20/2022

Inspection Photos



Photo 2. Facing northwest along the access road. The former road has not been reclaimed and soils are bare of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-06706 | Date: 7/20/2022

Inspection Photos



Photo 3. Facing north along the former road which dead ends at the well site location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-06706 | Date: 7/20/2022

Inspection Photos



Photo 4. Facing south at the location. The location has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-06706 | Date: 7/20/2022

Inspection Photos



Photo 5. Facing southwest at the location. There are areas of sparse vegetation and undesirable weeds (Kochia).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-06706 | Date: 7/20/2022

Inspection Photos



Photo 6. View of groundcover at the center of the location shows bare soils as well as undesirable weeds (Kochia).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-06706 | Date: 7/20/2022

Inspection Photos



Photo 7. Facing north at the surrounding undisturbed Buffalo grass pasture.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-06706 | Date: 7/20/2022