

Inspection Photos

API: 125-09762

Operator: ENERGY QUEST II LLC

Inspection Date: 7/20/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-09762 | Date: 7/20/2022

Inspection Photos



Photo 1. There is a fence that remains at the associated facility located by the County Road. Lat/Long:39.64564,-102.27091
The vegetation has not re-established in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-09762 | Date: 7/20/2022

Inspection Photos



Photo 2. Facing northwest along the former road. There is erosion along the two track road which has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-09762 | Date: 7/20/2022

Inspection Photos



Photo 3. Facing southwest toward the location. The location has not been reclaimed. The location is not stabilized and there are signs of erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-09762 | Date: 7/20/2022

Inspection Photos



Photo 4. There are degraded and displaced wattles that are now debris. BMP's must be installed and maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-09762 | Date: 7/20/2022

Inspection Photos



Photo 5. Facing northwest at the location. There are signs of erosion and soils are not stabilized. BMP's must be installed and maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-09762 | Date: 7/20/2022

Inspection Photos



Photo 6. Facing west at the location. There is a t-post and wood post that must be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-09762 | Date: 7/20/2022