

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/27/2022

Submitted Date:

07/28/2022

Document Number:

702500289

FIELD INSPECTION FORM

Loc ID 325837 Inspector Name: Klink, Alex On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.com	All SW field inspections
Telecky, Barbara		btelecky@blm.gov	Durango

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215452	WELL	PR	06/01/2019	CBM	067-07057	FISCHER-MARK FEDERAL A 1	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type OTHER

Comment: [Impacted material near lube oil spill prevention \(IMG 03\).](#)

Corrective Action: [Remove impacted material and dispose of in approved manner per rule 906 and 1002.f.](#)

Date: 08/12/2022

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type OTHER

Comment: [All equipment on location is enclosed by stock panel.](#)

Corrective Action:

Date: _____

Equipment:

corrective date

Type: Ancillary equipment # 3

Comment: [Telemetry, pump control panel, solar panel](#)

Corrective Action:

Date: _____

Type: Prime Mover # 1

Comment: [Gas powered.](#)

Corrective Action:

Date: _____

Type: Pump Jack # 1

Comment:

Corrective Action:

Date: _____

Type: Bird Protectors # 1

Comment: [Separator vent stack is screened properly.](#)

Corrective Action:

Date: _____

Type: Bradenhead # 1

Comment: [Bradenhead is accessible.](#)

Corrective Action:

Date: _____

Type: Gas Meter Run # 1

Comment: [Gas meter calibration is within the last year.](#)

Corrective Action:

Date: _____

Type: Flow Line # 3

Comment:	3" line from wellhead to separator, 1.5" line at separator, 3" line from gas meter run to off location.			
Corrective Action:			Date:	
Type: Vertical Heated Separator	# 1			
Comment:				
Corrective Action:			Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 215452 Type: WELL API Number: 067-07057 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Check Dams	Pass					
		Gravel	Pass			
Rip Rap	Pass					
Compaction	Pass					
Berms	Pass					
				Material Handling And Spill Prevention	Pass	
		Compaction	Pass			
Ditches	Pass					
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500290	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5814989