

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/28/2022

Submitted Date:

07/28/2022

Document Number:

702500298

**FIELD INSPECTION FORM**

Loc ID 313610 Inspector Name: Klink, Alex On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 46685  
Name of Operator: KINDER MORGAN CO2 CO LP  
Address: 1001 LOUISIANA ST SUITE 1000  
City: HOUSTON State: TX Zip: 77002

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		CO2Source_Regulatory@kindermorgan.com	<a href="#">All SW field inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293261	WELL	TA	03/06/2018	CO2	083-06634	GOODMAN POINT 12	TA

**General Comment:**

Inspector Alex Klink on site to witness MIT and conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	Area	Volume		corrective date
Type: Bradenhead	# 1			
Comment:	Bradenhead is accessible.			
Corrective Action:				Date:
Type: Flow Line	#			
Comment:	7 3/4" vent lines on south edge of location			
Corrective Action:				Date:

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 293261 Type: WELL API Number: 083-06634 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Results from MIT: Cast iron bridge plug set at 7795'. Test commenced at 12:05 PM. Casing pressure before test: 11.3 PSI. Casing pressure at start of test: 407.2 PSI. Casing pressure 5 min: 405.4 PSI. Casing pressure 10 min: 403.3 PSI. Casing pressure 401.9 PSI. Total pressure lost: 5.3 PSI.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
Compaction						
		Compaction				
		Gravel				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500300	Photo doc	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5815674">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5815674</a>