

# Inspection Photos

July 26, 2022

Operator: Beeman Oil & Gas Inc - #7125

Location ID: 438580

Location Name: Welker 6-92 /1-2H11

Inspection Document #: 702800491

Moffat County, CO

SESE Section 2 T6N R92W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Welker 6-92 /1-2H11  
Location ID: 438580



**Photo 1.** Photo taken from the tank battery shows Beeman Oil & Gas Inc. as the Operator listed on tanks and tank battery signage.



**Photo 2.** Photo taken from the Location access road shows Beeman Oil & Gas Inc. as the Operator listed on signage.



Inspection Photos  
Location Name: Welker 6-92 /1-2H11  
Location ID: 438580



**Photo 3.** Photo taken from the east of the Location shows concrete debris.



Inspection Photos  
Location Name: Welker 6-92 /1-2H11  
Location ID: 438580



**Photo 4.** Photo taken from the wellhead shows stained soils.



**Photo 5.** Photo taken from the west of the pumpjack shows stained soils.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800491

Inspection Photos  
Location Name: Welker 6-92 /1-2H11  
Location ID: 438580



**Photo 6.** Photo taken from the north of the Location shows a methanol tank. The secondary containment stock tank lacks wildlife protection BMPs. Safety labeling on the tank is faded and/or peeling and inadequate.



**Photo 7.** Photo taken from the well area shows a methanol tank lacking wildlife protection BMPs on the secondary containment device.



Inspection Photos  
Location Name: Welker 6-92 /1-2H11  
Location ID: 438580



**Photo 8.** Photo taken from the northwest of the Location shows an anchor marker in disrepair. Four anchor markers on Location were observed in disrepair.



Inspection Photos  
Location Name: Welker 6-92 /1-2H11  
Location ID: 438580



**Photo 9.** Photo taken from the southeast of the Location shows areas of the Location at the southwest not necessary for production operations which have not been reclaimed. Photo also shows weeds growing on Location and contributing to debris.



**Photo 10.** Photo taken from the northeast of the Location shows weeds have been cut and left on Location contributing to debris.



Inspection Photos  
Location Name: Welker 6-92 /1-2H11  
Location ID: 438580



**Photo 11.** Photo taken from the Location perimeter berm shows establishment of Canada thistle, a CO State List B Noxious Weed.



**Photo 12.** Photo taken from the Location perimeter berm shows establishment of Scotch thistle, a CO State List B Noxious Weed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800491

Inspection Photos  
Location Name: Welker 6-92 /1-2H11  
Location ID: 438580



**Photo 13.** Photo taken from the Location perimeter berm shows spotted and diffuse knapweed, CO State List B Noxious Weeds.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800491

Inspection Photos  
Location Name: Welker 6-92 /1-2H11  
Location ID: 438580



**Photo 14.** Photo taken from the south of the pump jack shows a variety of unused equipment stored on Location.



**Photo 15.** Refer to Photo 14 comment.

