

# Inspection Photos and Issue Report

7/27/2022

Operator: CAERUS PICEANCE LLC # 10456

Location #479149

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location #479149



**Photo 1:** Photos show additional material spills observed on the Location.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location #479149



**Photo 2:** Photo shows impacted soils due to spills from equipment.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location #479149



**Photo 3:** Photo taken from the perimeter stormwater ditch. Photo example showing topsoil (yellow arrow) in use as part of stormwater controls (ditch/berm) to manage runoff on the Location. Photo also provide example of areas where controls to stabilize and protect topsoil has degraded, resulting in topsoil eroding into ditch and mixing with subsoils.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location #479149



**Photo 4:** See comments under photo 3.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location #479149



**Photo 5:** Photos examples showing topsoil remains in use as part of the Locations perimeter stormwater controls, specifically, one of the three sediment traps on the Location. Photo also shows control has not been constructed with an engineered outlet to allow for proper stormwater discharge.

Inspection Photo  
Operator Name: CAERUS PICE  
Location #4791



**Photo 6:** Additional photo example showing topsoil in use as part of the perimeter's ditch and berm, as well as the sediment traps. See comments under photo 6.