



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type: Bradenhead

# 1

corrective date

Comment: plumbed to surface

Corrective Action:

Date:

Type: Ancillary equipment

# 1

Comment: electric

Corrective Action:

Date:

Type: Pump Jack

#

Comment:

Corrective Action:

Date:

Type: Prime Mover

# 1

Comment: electric motor

Corrective Action:

Date:

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 241341 Type: WELL API Number: 123-09130 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
This inspection does not nullify any orders or NOAV from the COGCC. At time of inspection weather conditions were warm, calm, overcast.	medinaj	08/01/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699504132	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5817393">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5817393</a>