

Inspection Photos

API: 071-07915

Operator: WAPITI OPERATING LLC

Inspection Date: 8/1/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07915 | Date: 8/1/2022

Inspection Photos



Photo 1. Facing west toward near the access road ascending the hillside. The culvert outlet has been washed out from recent storm event. It appears a larger culvert is needed along with larger rock rip/rap outlet protection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07915 | Date: 8/1/2022

Inspection Photos



Photo 2. The culvert inlet is filled in with sediment. It appears a larger culvert is needed at this area to handle stormwater coming off the road and drainage.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07915 | Date: 8/1/2022

Inspection Photos



Photo 3. There are signs stormwater is flowing down the road causing erosion. This area has been a problem before. A water bar may help in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07915 | Date: 8/1/2022

Inspection Photos



Photo 4. Facing west along the access road. Some of the rock check dams previously installed have washed out. Larger rock was likely needed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07915 | Date: 8/1/2022

Inspection Photos



Photo 5. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07915 | Date: 8/1/2022

Inspection Photos



Photo 6. There are still noxious weeds Hounds tongue which have not been controlled. The noxious weeds have already produced seed so the weeds will now need to be bagged and removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07915 | Date: 8/1/2022