

Inspection Photos

API: 071-09838

Operator: WAPITI OPERATING LLC

Inspection Date: 8/1/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09838 | Date: 8/1/2022

Inspection Photos



Photo 1. Facing southwest along the main road near the well site. There was a recent rain event that caused stormwater to flow across the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09838 | Date: 8/1/2022

Inspection Photos



Photo 2. The culvert outlet has eroded and needs to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09838 | Date: 8/1/2022

Inspection Photos



Photo 3. Facing toward the northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09838 | Date: 8/1/2022

Inspection Photos



Photo 4. Facing east toward the location at the upper cut slope area. Stormwater runoff is causing erosion. This area needs to be repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09838 | Date: 8/1/2022

Inspection Photos



Photo 5. There is deep channeling occurring along the cut slope which must be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09838 | Date: 8/1/2022

Inspection Photos



Photo 6. There are noxious weeds wilted along the roadside.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09838 | Date: 8/1/2022