

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

Good Housekeeping:

Type	OTHER		
Comment:	Stained Soil next to the Compressor & VRU needs to be removed. See attached photos		
Corrective Action:	“Properly dispose of oily waste in accordance with 905.e.”	Date:	08/12/2022
Type	OTHER		
Comment:	Oily Waste on Compressor skid needs to be removed. See attached photos.		
Corrective Action:	“Properly dispose of oily waste in accordance with 905.e.”	Date:	08/12/2022

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type				corrective date
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:		Date:		
Type: VRU	# 1			
Comment:				
Corrective Action:		Date:		
Type: Compressor	# 1			
Comment:	Air Compressor			
Corrective Action:		Date:		
Type: LACT	# 1			
Comment:				
Corrective Action:		Date:		
Type: Emission Control Device	# 5			

Comment:			
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:			Date:
Type: Compressor	# 1		
Comment: Booster			
Corrective Action:			Date:
Type: Bird Protectors	# 10		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	100 BBLS	PBV STEEL		,
Comment:	Share containment with crude oil tanks				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	10	3000 BBLS	STEEL AST		40.260100,-104.569100
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 481807 Type: TANK API Number: - Status: AC Insp. Status: AC

Producing Well

Comment: ac

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday 8/2/22 at approximately 0935hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Becker Ranch 5RU-TB Pad of PDC Energy, at Facility ID: 481807 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: Stained Soil next to the Compressor & VRU needs to be removed. "Properly dispose of oily waste in accordance with 905.e." With a corrective action date of 8/12/22 Oily Waste on Compressor skid needs to be removed. "Properly dispose of oily waste in accordance with 905.e." With a corrective action date of 8/12/22 See attached photos. Submit pictures on FIRR. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	burnsa	08/02/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699105815	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5818814