

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/01/2022

Submitted Date:

08/02/2022

Document Number:

707600129

FIELD INSPECTION FORM

Loc ID 310651 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10110
Name of Operator: GREAT WESTERN OPERATING COMPANY LLC
Address: 1775 SHERMAN STREET STE 3000
City: DENVER State: CO Zip: 80203

Findings:

15 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296335	WELL	PR	05/01/2021	GW	123-26749	PEPPLER 17-12	SI

General Comment:

This is a WELL / TANK BATTERY inspection.
Well(s): 1: Shut-In | SI.
Battery: Shut-down | Inactive.

Centralized Battery serves 2 Location IDs (310651, 310057).
(Well(s): 2: Shut-In | SI).

Location

Lease Road:			
	Type Access		
	comment: Adequate		
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
	Type TANK LABELS/PLACARDS		
	Comment:		
Corrective Action:			Date:
	Type BATTERY		
	Comment:		
Corrective Action:			Date:
	Type WELLHEAD		
	Comment:		
Corrective Action:			Date:

Emergency Contact Number:			
	Comment:		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
	Type WELLHEAD		
	Comment: Iron panel.		
Corrective Action:			Date:
	Type SEPARATOR		
	Comment: Surrounded by earth berms.		
Corrective Action:			Date:

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Type: Gas Meter Run	# 1	
Comment:	1: Gas Sales. Calibration card indicates NO calibration within last year. Last calibration: 06/18/2021. Inactive, no production.	
Corrective Action:		Date:
Type: Emission Control Device	# 1	
Comment:	Condensate tank(s) vapor line combustor(s). Controls condensate tank(s) vapors. Pilot(s): OFF. Inactive. Shut-down.	
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment:	At Battery site: 1: ECD scrubber.	
Corrective Action:		Date:
Type: Bird Protectors	# 2	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:	Appears plumbed to surface.	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		
Comment:	Centralized Battery serves 2 Location IDs (310651, 310057).				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS		
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	

Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment: Shares berms w/ condensate tanks.						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLs	STEEL AST		40.489739,-104.465512	
Comment: Equalizer line connects condensate tanks.						
Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment: Shares berms w/ produced H2O tank.						
Corrective Action:					Date:	
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities

Facility ID: 296335 Type: WELL API Number: 123-26749 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: Shut-In | SI.
Observed production valve(s) shut.
Locked-Out | LO.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 03/15/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/>						Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On MON 08/01/2022 at approximately 09:41 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: GREAT WESTERN OPERATING COMPANY LLC Location Name: PEPPLER-66N63W /17SWNW Location ID: 310651 Well Name(s): Peppler 17-12. API: 123-26749. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Shut-In SI. Battery: Shut-down Inactive.</p> <p>Centralized Battery serves 2 Location IDs (310651, 310057). (Well(s): 2: Shut-In SI).</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	08/02/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707600130	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5819161