

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/01/2022

Submitted Date:

08/02/2022

Document Number:

707600153**FIELD INSPECTION FORM**Loc ID 419494 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 2001 16TH STREET SUITE 900City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
419491	WELL	TA	04/01/2020	OW	123-32266	Peppler PC AA17-20	TA

General Comment:

This is a WELL inspection.
 Well(s): 1: Temporarily Abandoned | TA.
 Battery: Abandoned. ALL equipment removed.
 Abandoned Battery GPS coord: 40.484920 / -104.460460

Abandoned Centralized Battery formerly served 10 Location IDs
 (419566, 305753, 305758, 306260, 306263, 306264, 419444, 419449, 419494, 444901).
 (Well(s): 9: Temporarily Abandoned | TA ;1: Plugged & Abandoned | PA).

Location**Lease Road:**

Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 1		corrective date
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 419491 Type: WELL API Number: 123-32266 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Battery Abandoned. Disconnected from flowline.
Locked-Out, Tagged-Out | LOTO.
Yellow LTSI tag posted.
COGCC records last production: 06/2016.
SI/TA well per variance doc. #401474555. (NOBLE).

Form 4 on file. TA date: 12/05/2018. Approved.

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: 05/03/2021 Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment: Date of last Brhd test > 1yr.
Required reports not filed. Submit current Brhd test.
Submit reports per Rule 207.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On MON 08/01/2022 at approximately 12:30 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: PEPPLER PC /AA17-20 Location ID: 419494 Well Name(s): Peppler PC AA17-20. API: 123-32266. Location County: Weld County, Colorado</p> <p>Weather: Mostly Sunny, dry. While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Abandoned. ALL equipment removed. Abandoned Battery GPS coord: 40.484920 / -104.460460</p> <p>Abandoned Centralized Battery formerly served 10 Location IDs (419566, 305753, 305758, 306260, 306263, 306264, 419444, 419449, 419494, 444901). (Well(s): 9: Temporarily Abandoned TA ;1: Plugged & Abandoned PA).</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	08/02/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707600154	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5819297