



**Location**

Overall Good:

**Signs/Marker:**

	Type WELLHEAD		
	Comment: Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

	Type WELLHEAD		
	Comment: iron		
Corrective Action:		Date:	

**Equipment:**

		# 1		corrective date
Type: Bradenhead				
Comment:	<input style="width: 90%; height: 20px;" type="text"/>			
Corrective Action:			Date:	
Type: Plunger Lift		# 1		
Comment:	<input style="width: 90%; height: 20px;" type="text"/>			
Corrective Action:			Date:	

**Venting:**

Yes/No	NO		
Comment:	<input style="width: 90%; height: 20px;" type="text"/>		
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:	<input style="width: 90%; height: 20px;" type="text"/>		
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 284719 Type: WELL API Number: 123-23871 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment:

Corrective Action:  Date:

**COGCC Comments**

Comment	User	Date
Routine Inspection. No corrective actions were observed at the time of inspection. **Weather Conditions: sunny, dry ground	santistb	08/02/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679604904	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5819893">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5819893</a>