

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403125677

Date Received:  
08/03/2022

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

#### Additional Operator Contact:

Contact Name	Phone	Email
<u>MacLaren, Joe</u>		<u>joe.maclaren@state.co.us</u>
<u>Ferrin, Jeremy</u>		<u>jeremy.ferrin@state.co.us</u>
<u>-, Marcom</u>		<u>primarycontractor@marcomllc.net</u>
<u>Gorka, Ray</u>		<u>RGorka@kpk.com</u>
<u>Schlagenhauf, Mark</u>		<u>mark.schlagenhauf@state.co.us</u>
<u>Tautkus, Kevin</u>		<u>ktautkus@marcomllc.net</u>

### COGCC INSPECTION SUMMARY:

FIR Document Number: 691201639

Inspection Date: 07/26/2022

FIR Submit Date: 08/02/2022

FIR Status: \_\_\_\_\_

#### Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC

Company Number: 46290

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

#### LOCATION - Location ID: \_\_\_\_\_

Location Name: \_\_\_\_\_ Number: \_\_\_\_\_ County: \_\_\_\_\_

Qtrqr: SESW Sec: 11 Twp: 1N Range: 68W Meridian: 6

Latitude: \_\_\_\_\_ Longitude: \_\_\_\_\_

#### FACILITY - API Number: 05-123- -00 Facility ID: 482625

Facility Name: UPRR 43 Pan Am I #23 Number: \_\_\_\_\_

Qtrqr: SESW Sec: 11 Twp: 1N Range: 68W Meridian: 6

Latitude: \_\_\_\_\_ Longitude: \_\_\_\_\_

### CORRECTIVE ACTIONS:

1 CA# 163678

Corrective Action:

Date: 08/03/2022

Manage waste in compliance with Rule 913.b.(5)i-v, Operator's waste management plan, and COGCC Guidance 913.b.(5)B i-v.

Response: CA COMPLETED

Date of Completion: 08/02/2022

Operator Comment: In response to Field Inspection Report document #691201639, please note that the requested corrective actions have been completed. Attached is photo documentation that the excavated impacted soil is being managed in accordance with KPK's waste management plan and COGCC Rule 913-b.(5)i-v. Excavated soil is stockpiled in a bermed and lined containment area. Signage has been added indicating soil types.

COGCC Decision: \_\_\_\_\_

COGCC Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: To provide clarification to the general comment regarding KPK's leak identification method, KPK has responded that they did not use produced fluids to identify the leak as was inferred from the initial Form 19. Since KPK was initially unsure if the leak location was from a KPK-operated facility, KPK shut in nearby wells individually and evaluated for a response in the leak following a shut-in. KPK was able to determine that the leak was from the UPRR 43 Pan I#23 flowline once that well was shut in. The flowline then remained off and KPK initiated a spill response, including removal of fluid from the line. KPK's response to the spill is in accordance with their Spill Response Plan and did not contribute to further releases of produced fluids.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Kevin Tautkus

Signed: \_\_\_\_\_

Title: Project Manager

Date: 8/3/2022 2:22:40 PM

#### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403125715	Site Photographs
-----------	------------------

Total Attach: 1 Files