

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Monument Ridge Pad /

Location ID: 422286



Photo #7316 from entrance to location.



Photo #7317 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Monument Ridge Pad /

Location ID: 422286



Photo #7318 from entrance to location.



Photo #7320 2" flowline system that manifolds all 16 wells together.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Monument Ridge Pad /

Location ID: 422286



Photo #7321 It appears the 2" line has been added post location construction.



Photo #7324 2" flowline appears to have been added for liquid unloading operations.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Monument Ridge Pad /

Location ID: 422286



Photo #7325 2" line dumps into singular tank battery dump line.



Photo #7327 Only dump line into tank battery.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Monument Ridge Pad /

Location ID: 422286



Photo #7329 Oil or condensate staining down tank.



Photo #7331 Staining on top of tank indicates the tank has been over pressured.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Monument Ridge Pad /

Location ID: 422286




Photo #7333 Staining on top of tank indicates the tank has been over pressured.



Photo #7332 Staining on top of tank indicates the tank has been over pressured.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Monument Ridge Pad /

Location ID: 422286



Photo #7328 Loadline open ended.



Photo #7335 Unused equipment.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Monument Ridge Pad /

Location ID: 422286



Network: Jul 27, 2022 at 12:34:12 PM MD
Local: Jul 27, 2022 at 12:34:12 PM MD



Network: Jul 27, 2022 at 1:18:41 PM MD
Local: Jul 27, 2022 at 1:18:41 PM MD

Photo #7330 Stained gravel in tank containment.

Photo #7336 No form of velocity check in ditch.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Monument Ridge Pad /

Location ID: 422286



Photo #7338 No form of velocity checks in access road ditch.



Photo #7339 Rill erosion occurring in North West corner of location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Monument Ridge Pad /

Location ID: 422286



Photo #7340 Run on to location is not being controlled.



Photo #7341 Run on to location is not being controlled.