

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/27/2022

Submitted Date:

07/27/2022

Document Number:

699804741**FIELD INSPECTION FORM**Loc ID 334732 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

19 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283573	WELL	PR	04/15/2007	GW	045-11944	ENCANA PAYTON 20-1 (PD21)	PR
283574	WELL	PR	06/22/2006	GW	045-11945	ENCANA PAYTON 20-1BB (PD21)	PR
283575	WELL	PR	04/12/2007	GW	045-11946	ENCANA 21-4BB(PD21)	PR
283576	WELL	PR	04/19/2007	GW	045-11947	ENCANA 21-4 (PD21)	PR
283582	WELL	PR	04/21/2007	GW	045-11949	ENCANA 21-3 (PD21)	PR
283585	WELL	PR	04/10/2007	GW	045-11948	ENCANA 21-5BB (PD21)	PR
283590	WELL	PR	02/01/2011	GW	045-11950	ENCANA MAHAFFEY 16-13 (PD21)	PR
288928	WELL	PR	04/07/2007	GW	045-13623	ENCANA FEDERAL 16-14BB (PD21)	PR

General Comment:**COGCC Inspection Report Summary**

On Monday 7/25/22 at approximately 13:30 hours, I, Inspector Corey De Paolo,
Conducted an on-site inspection at CAERUS PICEANCE LLC ENCANA-67S95W /21NWNW.
Location #334732 in Garfield County Colorado.

This inspection is in response to complaint #403112337, #403112351, # 403112354 and #403112356.

While there, I observed normal production operations.

This is a summary of inspection report.

LocationOverall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include an attached storage tank. The storage tank is approximately 2'x3'x14' with an approximate capacity of 15 bbl. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-2615

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Livestock panels		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Plunger Lift	# 8		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 8		
Comment:			
Corrective Action:		Date:	

Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Summit midstream		
Corrective Action:			Date:
Type: Bradenhead	# 8		
Comment:	Pressure transducers located on all braden heads. All braden head valves are accessible.		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:	Separate containment					
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	3	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Separate containment				
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities						
Facility ID:	283573	Type:	WELL	API Number: 045-11944	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	283574	Type:	WELL	API Number: 045-11945	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	283575	Type:	WELL	API Number: 045-11946	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	283576	Type:	WELL	API Number: 045-11947	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	283582	Type:	WELL	API Number: 045-11949	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	283585	Type:	WELL	API Number: 045-11948	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	283590	Type:	WELL	API Number: 045-11950	Status: PR	Insp. Status: PR
Complaint						
Comment:	This inspection is in response to complaint #403112337, #403112351, #403112354 and #403112356					
Corrective Action:						Date:
Facility ID:	288928	Type:	WELL	API Number: 045-13623	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
Compaction						
Berms						
Gravel						
		Gravel				
Sediment Traps						
		Berms				
Ditches						
		Ditches				
		Check Dams				
		Sediment Traps				

Comment: Location appears to have some gravel throughout the location with light compaction. Places with light to no gravel are present on location. Light gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to storm water for comments.	depaoloc	07/27/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699804742	Photos for Insp. #699804741	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5820440