



MarCom Photo Template

4/5/2022 - 20220405 101540



20220405\_101540.jpg

Stained soil in excavation.

---



4/6/2022 - 20220406 130935



20220406\_130935.jpg

Damaged section of flowline.

---



4/6/2022 - 20220406 140107



20220406\_140107.jpg



4/6/2022 - 20220406 140248



20220406\_140248.jpg

Pipeline insert showing no damage or leaks.

---



4/6/2022 - 20220406 141545



20220406\_141545.jpg

Excavation of impacted soil.

---

