

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type WELLHEAD

Comment: Red AG fencing

Corrective Action:

Date: _____

Equipment:

corrective date

Type: Plunger Lift # 1

Comment:

Corrective Action:

Date: _____

Type: Ancillary equipment # 1

Comment: automation

Corrective Action:

Date: _____

Type: Bradenhead # 1

Comment: plumbed to surface

Corrective Action:

Date: _____

Venting:

Yes/No NO

Comment:

Corrective Action:

Date: _____

Flaring:

Type

Comment:

Corrective Action:

Date: _____

Inspected Facilities

Facility ID: 201810 Type: WELL API Number: 001-07214 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. At time of inspection weather conditions were warm, calm, some cloud coverage.	medinaj	08/03/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699504144	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5822005