

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

06/16/2022

Document Number:

403079799

Off-Location Flowline

The Flowline Report, Form 44, shall be submitted to register, report realignment, report removal from service, provide pre-abandonment notices, or report abandonment of Off-Location Flowlines, Flowline Systems, Produced Water Transfer Systems, or Crude Oil Transfer Lines or Systems as required by the 1100 Series Rules. The Form 44 shall also be submitted to register, report realignment, or report abandonment of Domestic Taps, and to report Grade 1 Gas Leaks from Flowlines per Rules 610 and 906.

Operator Information

OGCC Operator Number: 10651 Contact Person: Heather Mitchell
Company Name: VERDAD RESOURCES LLC Phone: (720) 845-6917
Address: 1125 17TH STREET SUITE 550 Email: regulatory@verdadresources.com
City: DENVER State: CO Zip: 80202

Is the Operator a Tier One member of the Utility Notification Center of Colorado (CO811) that participates in Colorado's One Call notification system? Yes [X] No [ ]

OFF LOCATION FLOWLINE

FLOWLINE ENDPOINT LOCATION IDENTIFICATION

Location ID: 320004 Location Type: Production Facilities
Name: GREAT WESTERN MELISSA Number: 1
County: ADAMS
Qtr Qtr: SESW Section: 8 Township: 1S Range: 65W Meridian: 6
Latitude: 39.975110 Longitude: -104.691086

Description of Corrosion Protection

Anode's are installed on steel flowlines. An annual water sampling program to determine corrosive fluids on all locations has been implemented. Poly lines are used wherever possible to prevent corrosion. Flowlines are sampled and truck treated with scale and corrosion inhibitor on an as needed basis. Failures are identified through AVO and annual inspections.

Description of Integrity Management Program

Integrity of flowlines are managed by conducting a 4-hour pressure test with installation of the line. Verdad adheres to rule 1104.j.2 by using a FLIR GF 320 infrared gas detection camera and an RD 7100 Line Locator. The Inspector annually conducts a survey using the camera to inspect for leaks along the entire length of the flowline. Other annual tests include static head tests on below-ground dump lines and function tests on isolation valves. Sites are monitored daily by lease operators trained to use sensory observation to inspect for leaks at the facility.

Description of the construction method used for public by-ways, road crossings, sensitive wildlife habitats, sensitive areas, and natural and manmade watercourses (i.e., open trench, bored and cased, or bored only), if applicable.

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 476230 Flowline Type: Wellhead Line Action Type: Abandonment Verification

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: \_\_\_\_\_ Location Type: \_\_\_\_\_ Well Site   
Name: GREAT WESTERN MELISSA Number: 13-8  
County: ADAMS No Location ID  
Qtr Qtr: NWSW Section: 8 Township: 1S Range: 65W Meridian: 6  
Latitude: 39.977360 Longitude: -104.695116

Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: \_\_\_\_\_ Pipe Material: \_\_\_\_\_ Max Outer Diameter:(Inches) \_\_\_\_\_  
Bedding Material: \_\_\_\_\_ Date Construction Completed: 07/21/2003  
Maximum Anticipated Operating Pressure (PSI): \_\_\_\_\_ Testing PSI: \_\_\_\_\_  
Test Date: \_\_\_\_\_

**OFF LOCATION FLOWLINE Abandonment Verification**

Date: 10/22/2021

**Abandonment Verification**

The abandoned Off-Location Flowline was located within the jurisdiction(s) of the following local government(s).

Jurisdiction	County	Municipality
County	ADAMS	N/A

**Description of Abandonment Verification:**

On 5/4/2022 the flowlines were flushed by forcing water on one end and vacuuming the water on the other end. Two water trucks were used in this operation. Flushed water was observed to be clear. The flowlines were exposed to atmospheric pressure.  
On 5/25/2022, it was observed that the flowlines were physically separated from the connection, risers were removed 3 feet below grade or to a depth of flowline, and flowline ends were sealed with Quickrete cement.

**OPERATOR COMMENTS AND SUBMITTAL**

Comments

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: \_\_\_\_\_ Date: 06/16/2022 Email: regulatory@verdadresources.com

Print Name: Heather Mitchell Title: Regulatory Manager

Based on the information provided herein, this Flowline Report complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: \_\_\_\_\_ Director of COGCC Date: \_\_\_\_\_

## Conditions of Approval

**COA Type**

**Description**

--	--

## Attachment Check List

**Att Doc Num**

**Name**

403079809	OFF-LOCATION FLOWLINE GIS SHP
403079810	THIRD PARTY VERIFICATION
403079817	ABANDONMENT IN PLACE DOCUMENTATION

Total Attach: 3 Files

## General Comments

**User Group**

**Comment**

**Comment Date**

		Stamp Upon Approval

Total: 0 comment(s)