

KP Kauffman - COGCC Inspection Photos
Location: AJ #1 Consolidation Flowline
Spill ID #482628 Date 07/28/2022



AJ #1 consolidated flowline; approximate release area; view North.



View of flowlines exposed in south bellhole excavation prior to repair; (1) 10" carbon steel AJ #1 consolidation flowline; (1) 2" carbon steel off location gas flowline.

KP Kauffman - COGCC Inspection Photos
Location: AJ #1 Consolidation Flowline
Spill ID #482628 Date 07/28/2022



Flowline repairs being completed at North bell hole excavation. 10" OD CS pipe to 4" OD HDPE pipe transition. Approximately 800' linear feet of 4" HDPE pipe sliplined through existing 10" AJ #1 consolidation flowline (across failure point at spill ID #482628).



Flowline repairs being completed at south bell hole excavation. 10" OD CS pipe to 4" OD HDPE pipe transition.