

Construction and Stormwater Inspection

Date: 07/26/2022

Operator: Verdad Resources LLC -10651

Location ID: 441041

Inspection Document #: 696105337

Weld County, CO

SWSW Section 30 T9N R59W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: MARTIN 3030-3031
Location ID: 441041



Photo 1. Location photo taken from entrance, facing west. Photo illustrates unconsolidated material around culvert (highlighted in red).

Inspection Photos

Location Name: MARTIN 3030-3031

Location ID: 441041



Photo 2. Location photo taken from entrance, facing north. Photo illustrates ditch and berm BMP installed during construction phase.

Inspection Photos

Location Name: MARTIN 3030-3031

Location ID: 441041



Photo 3. Location photo taken from northeastern portion, facing south. Photo illustrates unconsolidated material in ditch and berm BMP (highlighted in red).



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 696105337

Inspection Photos

Location Name: MARTIN 3030-3031

Location ID: 441041



Photo 4. Location photo taken from northeastern portion, facing southwest. Photo illustrates unconsolidated material in ditch and berm BMP (highlighted in red).

Inspection Photos

Location Name: MARTIN 3030-3031

Location ID: 441041



Photo 5. Location photo taken from northwestern portion, facing southwest. Photo illustrates topsoil stockpile has been temporarily stabilized with equipment tracking.

Inspection Photos

Location Name: MARTIN 3030-3031

Location ID: 441041



Photo 6. Location photo taken from northwestern portion, facing southeast. Photo illustrates unconsolidated material in ditch and berm BMP (highlighted in red).

Inspection Photos

Location Name: MARTIN 3030-3031

Location ID: 441041



Photo 7. Location photo taken from western portion, facing south. Photo illustrates ditch and berm BMP installed during construction phase.

Inspection Photos

Location Name: MARTIN 3030-3031

Location ID: 441041



Photo 8. Sediment trap photo taken from southwest portion of location, facing southeast. Photo illustrates sediment trap walls not properly stabilized (e.g. vertical) and unconsolidated material.

Inspection Photos

Location Name: MARTIN 3030-3031

Location ID: 441041



Photo 9. Ditch and berm photo taken from southern portion of location, facing west. Photo illustrates unconsolidated material in ditch (highlighted in red).

Inspection Photos
Location Name: MARTIN 3030-3031
Location ID: 441041



Photo 10. Ditch and berm photo taken from southeast portion of location, facing north. Photo illustrates unconsolidated material (highlighted in red).