

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/20/2022

Submitted Date:

08/09/2022

Document Number:

688312792

FIELD INSPECTION FORM

Loc ID 320674 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
KPK		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204420	WELL	PR	02/01/2022	GW	005-06505	FRICK, VIOLA 32-2	PR

General Comment:

[Crypto Mining Equipment Inspection](#)

Location

Lease Road:

	Type Access		
comment:	control weeds		
Corrective Action:	Comply with Rule 606.	Date:	08/23/2022

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:	on the ground (see attached photo)		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	303-825-4822	Date:	
Corrective Action:			

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

	#	corrective date
Type: Bradenhead	# 1	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:					
Corrective Action:					Date:

Paint

Condition	<input style="width: 95%;" type="text"/>
Other (Content)	<input style="width: 95%;" type="text"/>
Other (Capacity)	<input style="width: 95%;" type="text"/>
Other (Type)	<input style="width: 95%;" type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:		
Corrective Action:		Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 204420 Type: WELL API Number: 005-06505 Status: PR Insp. Status: PR

Producing Well

Comment: [pr 5/1/2022 reported as SI to COGCC database.](#)
[Form 4 Document #402924489 04 \(OBJ-VENT_FLARE\) -00](#)
[Attachment count: 3 IN PROCESS 2/25/2022 2/25/2022 KP KAUFFMAN COMPANY INC](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688312880	KPK Frick Viola 32-2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5824032