

Inspection Photos

API: 055-06285

Operator: CAPTUREPOINT LLC

Inspection Date: 8/8/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06285 | Date: 8/8/2022

Inspection Photos




Photo 1. Facing west toward the access road. There are noxious weeds along the road that need to be controlled. Red arrow → Scotch thistle



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06285 | Date: 8/8/2022

Inspection Photos



Photo 2. Facing northwest toward the location. There is numerous noxious weeds at the location that need to be controlled. The weeds have produced seed heads which should be cut and removed.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06285 | Date: 8/8/2022

Inspection Photos



Photo 3. Facing north toward the location. There is numerous noxious weeds at the location that need to be controlled. The weeds have produced seed heads which should be cut and removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06285 | Date: 8/8/2022

Inspection Photos



Photo 4. Facing northwest toward the well site. Red arrow points to Leafy spurge a List B noxious weed that needs to be controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06285 | Date: 8/8/2022

Inspection Photos



Photo 5. List B noxious weed → Leafy Spurge



Photo 6. List B noxious weed → Scotch thistle



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources