

Inspection Photos

API: 055-06219

Operator: PETROGLYPH OPERATING CO

Inspection Date: 8/8/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06219 | Date: 8/8/2022

Inspection Photos



Photo 1. Facing southeast along the access road. There is erosion occurring along the road that has not been repaired and has worsened since previous inspection. Previous corrective action not completed



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06219 | Date: 8/8/2022

Inspection Photos



Photo 2. Facing southeast toward the location. There is noxious weeds shown red arrow which have seeded out. → Diffuse knapweed



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06219 | Date: 8/8/2022

Inspection Photos



Photo 3. Facing east toward the location. There is noxious weeds shown red arrow which have seeded out. → Diffuse knapweed



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06219 | Date: 8/8/2022

Inspection Photos



Photo 4. Facing toward the fill slope. There erosion occurring along the fill slope which is not stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06219 | Date: 8/8/2022

Inspection Photos



Photo 5. Facing toward the fill slope. There erosion occurring along the fill slope which is not stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06219 | Date: 8/8/2022

Inspection Photos



Photo 6. Facing toward the east side of the location. The vegetation is well established at the eastern portion of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06219 | Date: 8/8/2022