

Inspection Photos

Location Name: Silver Spur Minerals 35-2H

API: 05-057-06490

Date: July 25, 2022



Location sign off of Hwy 14.



Well sign.



Inspection Photos

Location Name: Silver Spur Minerals 35-2H

API: 05-057-06490

Date: July 25, 2022



Equipment stored on Location. Pipe and tubing noted in previous inspections has been removed.



Pipe and tubing noted in previous inspections has been removed.



Inspection Photos
Location Name: Silver Spur Minerals 35-2H
API: 05-057-06490
Date: July 25, 2022



Tank signage, labels, and placards are illegible



Tank labels is illegible.

Inspection Photos

Location Name: Silver Spur Minerals 35-2H

API: 05-057-06490

Date: July 25, 2022



Tank 0030, staining beneath hammer unions. Possible weeping of fluids from valve.



Tank 0030, staining beneath hammer unions.



Inspection Photos

Location Name: Silver Spur Minerals 35-2H

API: 05-057-06490

Date: July 25, 2022



Staining from May 2021 gas leak/vent and condensate around wellhead. Trash/unused equipment (wrenches, needle valve and pressure gauge).



Staining from May 2021 gas leak/vent and condensate around wellhead. Apparent newer material imported over previously impacted area.



Inspection Photos

Location Name: Silver Spur Minerals 35-2H

API: 05-057-06490

Date: July 25, 2022



Area where oil heater was positioned. Not the hydrocarbon stained soil. Per Rule 911.a. operator shall submit a Form 27 prior to the removal of facility equipment.



Area where oil heater and associated equipment once were positioned. Per Rule 911.a. operator shall submit a Form 27 prior to the removal of facility equipment. Note: unmarked risers and piping.



Inspection Photos

Location Name: Silver Spur Minerals 35-2H

API: 05-057-06490

Date: July 25, 2022



Area where oil heater and associated equipment once were positioned. Per Rule 911.a. operator shall submit a Form 27 prior to the removal of facility equipment. Note: unmarked risers and piping, trash and debris.



Area where oil heater and associated equipment once were positioned. Stained soil noted in previous inspections.

