

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/05/2022

Submitted Date:

08/09/2022

Document Number:

701103439

FIELD INSPECTION FORMLoc ID 332715 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 95520

Name of Operator: WESCO OPERATING INC

Address: 120 S DURBIN STREET

City: CASPER State: WY Zip: 82602

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

5 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Morgan, John		john.morgan@state.co.us	
Kirkwood, Thomas	307-577-5328	tomk@kirkwoodcompanies.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222158	WELL	IJ	05/01/2022	DSPW	081-05065	MAUDLIN GULCH UNIT 2	AC
223209	WELL	PR	05/01/2022	OW	081-06572	MAUDLIN GULCH UNIT 27	PR

General Comment:

COGCC UIC Yearly Inspection Report Summary

Location is in a High Priority Habitat Area.

During this inspection the following compliance issues were observed:

• No api # on well signs.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	No api # on well signs.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	10/15/2022
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911	
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Pump Jack	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
------	--	--

Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 222158 Type: WELL API Number: 081-05065 Status: IJ Insp. Status: AC

Underground Injection Control

UIC Violation: Maximum Injection Pressure: 1720

UIC Routine

Inj./Tube: Pressure or inches of Hg (e.g. 30 psig or -30" Hg) Previous Test Pressure MPP
TC: Pressure or inches of Hg 0 Previous Test Pressure Inj Zone: SNDC
Brhd: Pressure or inches of Hg 0 Previous Test Pressure Last MIT: 08/10/2020
AnnMTReq:

Comment: Last MIT 8/10/2020 doc # 402467449
Injection pressure valve shut off to gauge.

Corrective Action: Date:

Method of Injection: PUMP FEED

Test Type: Tbg psi: Csg psi: BH psi:

Insp. Status:

Comment:

Corrective Action: Date:

Facility ID: 223209 Type: WELL API Number: 081-06572 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
				Material Handling And Spill Prevention		
		Ditches				
Gravel						
		Compaction				
		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701103440	Inspection 701103439 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5824893