

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403134167

Date Received:  
08/12/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Romana Cowden

720-951-5895

COGCC.inspections@caerusoilandgas.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696203901

Inspection Date: 07/27/2022

FIR Submit Date: 07/29/2022

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 479214

Location Name: BJU N23-496 Central Delivery Point Number: Production Pad County: \_\_\_\_\_

Qtrqtr: SESW Sec: 23 Twp: 4S Range: 96W Meridian: 6

Latitude: 39.680578 Longitude: -108.138397

FACILITY - API Number: 05-045-00 Facility ID: 479214

Facility Name: BJU N23-496 Central Delivery Point Number: Production Pad

Qtrqtr: SESW Sec: 23 Twp: 4S Range: 96W Meridian: 6

Latitude: 39.680578 Longitude: -108.138397

CORRECTIVE ACTIONS:

1 CA# 163648

Corrective Action: Comply with Rule 1002.f, 1002.b and 1002.c; implement perimeter stormwater and erosion control BMPs to manage runoff, and to allow for sediment laden-free discharge from the Location; ensure BMPs are installed accordance with good engineering practices, are adequate for the sites conditions, and are maintained in a proper functioning conditions. Ensure stockpiled topsoil is not incorporated with the BMPs, and remain protected.

Date: 09/10/2021

Response: CA COMPLETED

Date of Completion: 07/27/2022

The location, including perimeter stormwater controls, were constructed utilizing industry standard operating

Operator  
Comment:

procedures, best management practices and standards permitted with BLM & COGCC at the time of approval. The stormwater controls measures were engineered to contain and disperse stormwater through infiltration, not surface discharge. Topsoil is not utilized as a perimeter control. Topsoil is stockpiled around the location. Inside the topsoil stockpiles, subsoils were cut to create a diversion ditch and a berm was constructed on the interior of the ditch using subsoils. Perimeter Sediment Control Logs are in place to mitigate the potential for sediment laden discharge from the location, acting as the disturbances perimeter control measure of the disturbance. When interim reclamation operations are conducted and topsoil is spread, grade will be returned to a natural horizon change from subsoils to topsoil.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden

Signed: \_\_\_\_\_

Title: EHS

Date: 8/12/2022 8:33:53 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

--	--

Total Attach: 0 Files