

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403134050

Date Received:

08/12/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 3 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Romana Cowden

Phone

720-951-5895

Email

cogcc.inspections@caerusoilandgas.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696203898

Inspection Date: 07/27/2022

FIR Submit Date: 07/29/2022

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 479149

Location Name: BJU Number: B26-496 County: _____
Pad

Qtrqtr: NENW Sec: 26 Twp: 4S Range: 96W Meridian: 6

Latitude: 39.677052 Longitude: -108.138400

FACILITY - API Number: 05-045- -00 Facility ID: 479149

Facility Name: BJU Number: B26-496
Pad

Qtrqtr: NENW Sec: 26 Twp: 4S Range: 96W Meridian: 6

Latitude: 39.677052 Longitude: -108.138400

CORRECTIVE ACTIONS:

3 CA# 163647

Corrective Action: Comply with Rules 1002.b.(2), 1002.c, and implement BMPs to stabilize/protect salvaged soils, and to ensure soil horizons remain properly segregated from separate soil horizons.

Date: 09/10/2021

Response: CA COMPLETED

Date of Completion: 07/27/2022

Operator Comment: Topsoil stock piles were hydroseeded September 2021 during initial construction; it was re-applied summer 2022. Desirable vegetation is beginning to establish. Topsoil is inspected routinely during scheduled stormwater inspection under CDPHE COR400000 General Construction Stormwater Permit, and we will continue to monitor for degradation, mixing with subsoils and wind and water erosion. Any issues identified during inspection will be

repaired per our maintenance program.

COGCC Decision: **Not Approved**

COGCC Representative: Inspections observed topsoil stockpiles in use as part of the Location's perimeter stormwater BMPs (ditch/berm and sediment traps/ponds); this does not comport with COGCC 1002 Rules and Operator has been notified accordingly on multiple occasions; Operator has not provided any documentation that this compliance issue has been resolved.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden

Signed:

Title: EHS

Date: 8/12/2022 7:10:27 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

403134050	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files