

Inspection Photos

API: 061-06867

Operator: MULL DRILLING COMPANY INC

Inspection Date: 8/10/2022



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06867 | Date: 8/10/2022

Inspection Photos



Photo 1. Facing northeast along the access road. There was road work performed along the access road. It is still a concern that stormwater may pool along low areas of the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06867 | Date: 8/10/2022

Inspection Photos



Photo 2. Facing west toward the location. Areas of erosion have been repaired. Areas along the roadside shown at red arrow need to be stabilized and seeded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06867 | Date: 8/10/2022

Inspection Photos



Photo 3. Facing toward the tank battery. A metal containment has been installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06867 | Date: 8/10/2022

Inspection Photos



Photo 4. Facing southwest at the location. Unused areas of the location need to be reclaimed and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06867 | Date: 8/10/2022

Inspection Photos



Photo 5. Facing northeast at the location. Unused areas of the location need to be reclaimed and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06867 | Date: 8/10/2022